Work Order I January-07-14 3:03:	D 110789 31 PM 3 5	64-13	*1-	10789*							Page 1
Revision ID:	64-13 B 1 I	0789	Accept	*N900	<b>040</b>	100	<b>)</b> * <sup>s</sup>	Setup	Start Stop	!7.	S1* S2*
Start Date: 1/07 Required Date: 1/07 Reference:		.,	*11*	Cust Item l Customer:	D:					,	
	ocess Plan: MLJ	Date: 14-01-0	Tooling: SPC (Y/N):		ate:		]	Run	Start Stop	*NI	R1* R2*
Sequence ID/ Work Center ID	Operation Description		Set Up/ Run Hou	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr										
D3564	Rev D										
*100  *100* Waterjet  FLOW CNC Waterjet	FLOW WATER JET  Memo 1-Cut as p Deburr if	per Dwg D3564 Dwg Rev:_ necessary	0.00 0.00 Prog Rev:					-	<u>U</u>		Ae 14.01.2-
110 <b>*110*</b> QC Quality Control	QC2- Inspect parts off  Memo	machine FAI/FAIB	0.00						<u>ŏ-</u>		Ac. 14.01.2
120 <b>*1 2 0 *</b>	QC8- Inspect parts - s	econd check	0.00 GA 1. 9- 0.00				FIL	)			
QC.	Memo		0.00								

Quality Control

DQA:			Date:										TRAC
QA Closed:			Date:			WORK ORDER NON-	-CC	ONFO	RMANCE / UPD		ork Order up	date only	AEROSPACE
Work Orde	· ·					DISPOSITION				AGAINST DE	PARTMENT/	PROCESS	
WORK OTGE	٠				_	Rework			Skid-tube (	Crosstube	]	Water Jet	Engineering
Part N	10.					Scrap			~ <del>~</del>	Small Fab	4	d. Eng. Coor.	Quality
NCR N	Ю.					Use-as-is Suspected Unapproved		Thern	noforming C	Finishing omposite	Rec/Stor	e/Packaging Supplier	Other
Root					Desci	ription of work order update	l	nitial	Action		Sign &		, ,
Cause		Date	Step	Qty		or non-conformance	Ch	ief Eng	Descripti	ion	Date	Verification	QC Inspector
Design Doc/Data													
Equip/Tooling													
Handling/Pre													
Material													
Operator													
Offset/Setup			:										
Process													
Supplier									,				
Training			:	i i									
Transport													
Unapproved													
							FAI	ULT CA	TEGORY				
Landi	ng (	Gear				General							
		Bending				Bend		Folio/F	Program		Outside Dim	ensions	Pressure/Forced
		Centre No	ot Concer	ntric		BOM/Route		Grain			Over/Under	tolerance	Set-up
		Cracks				Broken/Damage/Defect		Hardwa	are		Part Incorred	:i	Temperature/Cure
		Crimp/Kir	nk/Ripple	/Wave		Burrs		Inspect	ion Incomplete/Unqua	alified	Part Lost/Mi	ssing	Weld
		Cuffs				Contamination		Instruc	tions Incomplete/Uncl	ear	Part Moved		Wrong Stock Pulled
	Г	Crushing				Countersink		Misali	gned/off center		Positioned W		<del></del>
		Heat Trea	it			Cut Too Short		Mislab	eled		Power Loss/S	Surge	Other
		Inspectio	n Strip in	Tube		Drawing		Misrea	d	-			
		Marks/Ch	atter			Drill Holes		Off-set					
		Turning S	equence			Finish		Out of	Calibration				
		Wave/Tw	ist in Tub	oe e		Fit/Function		Out of	Sequence				

Wo	rk	Order	ID ·	110789
***	, n	. , , , , , , , ,		1 1 11 / (7 7

\*110789\*

Page 2

January-07-14 3:03:31 PM Accept Item ID: D3564-13 \*N900040100\* Setup Start **Revision ID:** Stainless Steel Wearpad Fwd Item Name: \*10\* **Start Date: Start Otv:** 10.00 1/07/14 **Cust Item ID:** Required Date: 1/07/14 Rea'd Otv: 10.00 \*10\* Customer: Reference: Run Start **Approvals:** Process Plan: Date: Tooling: Date: Stop OC: Date: SPC (Y/N): Date: Sequence ID/ **Operation** Set Up/ Reject Reject Tool ID Tool # Plan Accept Insp. **Work Center ID** Description Code **Qty** Oty Number **Run Hours** 130 0.00 NC BRAKE \*130\* DAS Brake NC 0.00 30 9-89 Brake NC Deburr if necessaryForm on Brake as per Dwg D3564 using Jigs DT 8179 140 QC5- Inspect part completeness to step on W/O \*140\* QC Memo **Quality Control** 150 0.00 11 \$ 14-2-3 358 \*150\* Powdercoat Memo Powder Coating

DQA:			Date:			WORK OPPER NON	~		DAAANGE / LU	DDATE					DART
QA Closed:			Date:			WORK ORDER NON-	-C(	JNFO	RIVIANCE / UI		Wo	ork Order up	date only		AEROSPACE
Wed od						DISPOSITION				AGAINST	DE	PARTMENT	/PROCESS		
Work Orde	er: .					n			cutat Audio -	C		1	\4/n+n-1n+		F.,
Dort N	اما					Rework			Skid-tube	Crosstube Small Fab		D=0	Water Jet		Engineering
Part N	NO				_	Scrap Use-as-is			Machining noforming	Finishing			d. Eng. Coor. e/Packaging		Quality Other
NCR N	lo.					Suspected Unapproved		inen	Large Fab	Composite		Nec/3to	Supplier		Other
							1		, u	' [		J	,,,		<u> </u>
Root					Desci	ription of work order update	l	nitial	Act	ion		Sign &			
Cause		Date	Step	Qty		or non-conformance	Ch	ief Eng	Descr	ription		Date	Verification	1	QC Inspector
Design		:													
Doc/Data															
Equip/Tooling															
Handling/Pre															
Material						!									
Operator						•									
Offset/Setup															
Process			,				Ì								
Supplier															
Training															
Transport															
Unapproved							L,	_		·····		<u></u>			
							FA	ULT CA	TEGORY						
Landi	ng (	1			_	General		1		r		٦			•
		Bending				Bend	L	4	Program			Outside Dim			Pressure/Forced
	L	Centre No	ot Concer	ntric	<u> </u>	BOM/Route		Grain				Over/Under	tolerance		Set-up
	<u> </u>	Cracks				Broken/Damage/Defect		Hardwa	are			Part Incorre	Cĺ		Temperature/Cure
	<u> </u>	Crimp/Kir	nk/Ripple	/Wave	<u> </u>	Burrs	Ŀ	Inspect	ion Incomplete/Ur	nqualified		Part Lost/Mi	-		Weld
		Cuffs				Contamination		4	tions Incomplete/l	Jnclear		Part Moved			Wrong Stock Pulled
		Crushing				Countersink		Misali	gned/off center			Positioned V	· ·		•
		Heat Trea				Cut Too Short		Mislab	eled			Power Loss/	Surge		Other
		Inspectio		Tube		Drawing		Misrea	d						
	L	Marks/Ch	natter			Drill Holes		Off-set							
		Turning S				Finish	L	Out of	Calibration						
		Wave/Tw	ist in Tub	oe .		Fit/Function		Out of	Sequence						

Work Ord January-07-14				*110	789*						Page 3
Item ID: Revision ID: Item Name:	D3564-13 Stainless Sta	eel Wearpad Fwd		Accept	*N900	<b>040</b>	100	)*	Setup Sta	17	S1* S2*
Start Date: Required Dat Reference:	1/07/14 <b>e:</b> 1/07/14	Start Qty: 10.00 Req'd Qty: 10.00	*10* *10*		Cust Item l Customer:	D:					
Approvals:	Process P	Plan:	Date:	Tooling:	D	ate:	_		Run Sta	rt *N	R1*
	QC:		Date:	SPC (Y/N):	D	ate:			Sto	<sup>p</sup> *N	R2*
Sequence ID/ Work Center 160 *1 60* OC Quality Control	ID	Operation Description QC3- Inspect Part Finish Memo		Set Up/ Run Hoùrs 0.00 27 0.00 44 2	Tool ID	Tool#	Plan Code	Accep Qty	t Reject Qty	Reject Number	Insp.
170 <b>*17</b> 0*		ldentify as per dwg & Sto	ck Location: FG	0.00				110	l	10	12-U

180

QC21- Final Inspection - Work Order Release

0.00

0.00

\*1 20\*

Packaging

Packaging

0.00

Quality Control

Memo

Memo

ML 5 14-02-05

DAS 26 9-89

DQA:			Date:							100 4 7 5					DART
QA Closed:			Date:			WORK ORDER NON	-C(	NFOI	KMANCE / U		Woi	rk Order up	date only		AEROSPACE
Q ( Closeu.			- Dute.							***			•		
Work Orde	er:					DISPOSITION				AGAINST	DEP	ARTMENT	PROCESS		
	•				<del></del> .	Rework			Skid-tube	Crosstube			Water Jet		Engineering
Part N	۱o.					Scrap		ı	Machining	Small Fab	$\Box$	Pro	d. Eng. Coor.	╗	Quality
	•	*				Use-as-is		Thern	noforming	Finishing		Rec/Stor	e/Packaging		Other
NCR N	۱o.					Suspected Unapproved			Large Fab	Composite			Supplier		
	•														
Root					Desci	ription of work order update	l	nitial		ction		Sign &			
Cause		Date	Step	Qty		or non-conformance	Ch	ief Eng	Desc	ription		Date	Verification	1	QC Inspector
Design	Ш						1								
Doc/Data	Щ														
Equip/Tooling							ļ					:			
Handling/Pre					·				i						
Material															
Operator				ŀ							- 1				
Offset/Setup															
Process															
Supplier										•					
Training	Щ								į		1				
Transport	Ш														
Unapproved			<u> </u>												
							FA	ULT CAT	regory			<b>-</b>			
Landi		1			_	General	_	1 ,_		1	—		. [		L 6.
	_	Bending	_		-	Bend	$\vdash$	4	rogram			Outside Dim		_	Pressure/Forced
		Centre No	ot Concer	ntric	-	BOM/Route	$\vdash$	Grain			-	Over/Under			Set-up
		Cracks			-	Broken/Damage/Defect	$\vdash$	Hardwa			Н	Part Incorred			Temperature/Cure
	_	Crimp/Kir	nk/Ripple	/Wave		Burrs	<u> </u>		ion Incomplete/L	•	_	Part Lost/Mi	-		Weld
	_	Cuffs			$\vdash$	Contamination	-	4	tions Incomplete		ш	Part Moved			Wrong Stock Pulled
		Crushing			<u> </u>	Countersink	-	1 -	ned/off center		$\vdash$	Positioned V			l
	<u> </u>	Heat Trea			.	Cut Too Short	<u> </u>	Mislabe			Ш	Power Loss/	Surge		Other
	$\vdash$	Inspectio		fube	<u> </u>	Drawing	$\vdash$	Misread			-				
	<u> </u>	Marks/Ch			<u> </u>	Drill Holes	$\vdash$	Off-set			-				
	<u></u>	Turning S			<u> </u>	Finish	_	4	Calibration		-				
		Wave/Tw	ist in Tub	e	i	Fit/Function		Out of !	Sequence						

Work Order ID:

110789

Parent Item:

D3564-13

Parent Item Name:

Stainless Steel Wearpad Fwd

**Start Date: 1/07/14** 

Required Date: 1/07/14

Start Oty: 10.00

Required Qty: 10.00

Comments:

IPP Rev:A

New Issue 07-03-08 ec

IPP Rev:B

As per Rev C 07-07-09 JLM

IPP Rev:C

As per Rev D 07-09-09 JLM Verified By:EC

IPP Rev:D Comme

Comments revised on Step 5, 6 per B44657 09-02-04 KJ Verified By:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
<b>M304S16GA</b> 304/316 Sheet .063		Purchased	No			100	sf	330.8470	0.222	<del>2.336842</del>	A	14.0	1.27
				Location		Loc Qty	<u>Lo</u>	c Code					
				MAT020		330.847			·				
				M12	6915	10.847				<del>- (1</del>			
				M12	7821	320			<u>12</u>	7821 -	<del></del>	2.4	

DQA:			Date:			WORK ORDER NON-	cc	NIEO	DRAANCE / II	IDDATE				DART
QA Closed:			Date:			WORK ORDER NON-	-	JINFO	NIVIAINCE / U		Wo	ork Order up	date only	AEROSPACE
Work Orde						DISPOSITION				AGAINST	DE	PARTMENT,	PROCESS	
Work Orde  Part N  NCR N	lo.					Rework Scrap Use-as-is Suspected Unapproved			Skid-tube  Machining  noforming  Large Fab	Crosstube Small Fab Finishing Composite		4	Water Jet d. Eng. Coor. re/Packaging Supplier	Engineering Quality Other
Root					Desci	ription of work order update	l	nitial	Ac	ction		Sign &		
Cause		Date	Step	Qty		or non-conformance		ief Eng		ription		Date	Verification	QC Inspector
Design Doc/Data Equip/Tooling Handling/Pre Material Operator Offset/Setup Process Supplier Training Transport Unapproved														
опарргочец						ille	FΔI	ULT CA	Ι ΓEGORY				<u>!</u>	.1
Landii	ng (	 Gear				General							· · · · · · · · · · · · · · · · · · ·	
Landi		Bending Centre No Cracks Crimp/Kin Cuffs Crushing Heat Trea Inspection Marks/Ch Turning S	nk/Ripple t n Strip in natter	/Wave		Bend BOM/Route Broken/Damage/Defect Burrs Contamination Countersink Cut Too Short Drawing Drill Holes Finish		Grain Hardwa Inspect Instruct Misalia Mislaba Misrea Off-set	ion Incomplete/U tions Incomplete/ gned/off center eled d	/Unclear		Outside Dim Over/Under Part Incorred Part Lost/Mi Part Moved Positioned V Power Loss/	tolerance ct ssing Vrong	Pressure/Forced Set-up Temperature/Cure Weld Wrong Stock Pulled Other
		Wave/Tw	ist in Tub	e		Fit/Function		Out of	Sequence	·				

DART AEROSPACE LTD	Work Order:	110789
Description: Wearshoe	Part Number:	D3564-13
Inspection Dwg: D3564 Rev: D		Page 1 of 1

## FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
7.00	+/-0.030	7.00	•		7	JKM-06
2.432	+/-0.010	2.434	_		V	JKM-06
3.227	+/-0.010	3.227	1		V	
3.500	+/-0.010	3,500	_		τ	
0.300 x 0.300	+/-0.010	.300x.300	_		V	
Ø0.188	+0.005/-0.001	188	-		V	
0.063	+/-0.010	1059	-		V	
	····					
					· · ·	
			-			
	h		·			

Measured by:	Audited by: DAS	Prototype Approval:	N/A
Date: 14.01.27	Date: 9-89 14/4/27	Date:	N/A

Rev	Date	Change	Revised by	Approved
Α	07.04.02	New Issue	KJ/JLM	
В	07.07.18	Dimensions updated per Dwg Rev. C	KJ/JLM 1.A	
С	08.02.28	Dwg Rev updated	KJ/DD	787





